

DIAGNOSIS AND TESTING (Continued)

PINPOINT TEST F: DIAGNOSTIC TROUBLE CODE: 639 INSUFFICIENT INPUT FOR TRANSMISSION SPEED SENSOR (Continued)

TEST STEP	RESULT	ACTION TO TAKE
F2 CHECK HARNESS CONNECTIONS		
<ul style="list-style-type: none"> Check that vehicle harness connector is fully engaged on transaxle TSS connector. Check that vehicle harness connector terminals are fully engaged in connector. Are connectors/terminals fully engaged? 	Yes No	GO to F3. SERVICE as required.
F3 TRANSAXLE FUNCTIONAL TEST		
<ul style="list-style-type: none"> Disconnect vehicle harness at TSS sensor. CAUTION: Do not pry on the connector. Pull vehicle harness connector. Connect Rotunda Transmission Tester 007-00085 or equivalent onto TSS sensor. Connect voltmeter positive lead to +TSS and negative lead to -TSS. Set voltmeter to AC. Perform TSS Function Test. Monitor voltmeter. Does voltage increase with an increase in vehicle speed? 	Yes No	REFER to the Powertrain Control/Emissions Diagnosis Manual ³² to diagnose vehicle harness or PCM concerns. GO to F4.
F4 CHECK RESISTANCE OF TRANSMISSION SPEED SENSOR (TSS)		
NOTE: Refer to Transmission Tester for terminal locations. <ul style="list-style-type: none"> Connect ohmmeter negative lead to +TSS jack and positive lead to -TSS jack on tester. This is to test TSS sensor. Record resistance. Is resistance between 100-200 ohms? 	Yes No	GO to F5. REPLACE sensor. RERUN TSS Function Test.

³² Can be purchased as a separate item.