## **DIAGNOSIS (Continued)**

<b>CLUTCH DIAGNOSIS (Continue</b>	(d)	ł
-----------------------------------	-----	---

CONDITION	POSSIBLE SOURCE	ACTION
Clutch Does Not Disengage     Properly	Improper clutch pedal travel.     External linkage worn or damaged.	<ul> <li>Service or replace linkage parts a required. Refer to Section 08-02.</li> <li>Remove transaxle. Verify torque or pressure plate bolts. Tighten bolts</li> </ul>
	Clutch components inside clutch housing worn or damaged.	to 33 N·m (24 Lb-Ft) if required. Check for damaged or worn clutch pressure plate, release bearing, release lever or release shaft pivot.
	Loose clutch pressure plate bolts.	<ul> <li>Check for warped or contaminated clutch disc.</li> </ul>
O BOWASE	2,177 16:27:32	Verify clutch disc hub spline free movement on input shaft spline — lubricate sparingly. Service or replace as required.
Clutch is Noisy When Pedal is Depressed (Noise Continues as Long as the Pedal is Held Down.)	Damaged release bearing.	Remove transaxle and replace release bearing. Inspect the release fingers and replace the
	Flywheel housing out of alignment.	pressure plate assembly as required.  Align housing.
Clutch Slips After the Pedal is Fully Released	Release linkage inside flywheel housing binding or damaged.      Total and the second se	<ul> <li>Lubricate with Premium Long-Life Grease XG-1-C (ESA-M1C75-B) or equivalent. Service or replace linkage parts as required. Refer to</li> </ul>
#0	Clutch facing excessively worn.	Section 08-02.  Remove transaxle. Check pressure plate and clutch disc for wear and contamination. Replace as required.
Clutch Squeaks or Scrubs When the Pedal is in Motion	<ul> <li>Clutch release linkage — lack of lubrication, binding, interference, worn or kinked.</li> <li>Lack of lubrication on the clutch release shaft bushing, lower bosses and lever to release bearing contact.</li> </ul>	Lubricate with Premium Long-Life Grease XG-1-C (ESA-M1C75-B) or equivalent. Service or replace as required.     Remove transaxle and release bearing. Lubricate with Premium Long-Life Grease XG-1-C (ESA-M1C75-B) or equivalent on
ET LETTER I I I TIL HANTING VI I I AND PORTUGEN EN TENETINGEN SANT SANT SANT VI I AND VI I AND VI I AND VI I A	<ul> <li>Lack of lubrication in the clutch release bearing bore and the transaxle release bearing guide.</li> <li>Flywheel housing out of alignment.</li> <li>Binding clutch cable.</li> </ul>	bushing and other areas. Lubricate with Premium Long-Life Grease XG-1-C (ESA-M1C75-B) or equivalent, accordingly. Align housing. Replace clutch cable. Do not lubricate. Refer to Section 08-02.
Noise When Clutch Pedal is Depressed	Clutch interlock switch.	<ul> <li>Inspect interlock switch activating rod for binding or excessive noise.</li> <li>Replace switch if necessary.</li> </ul>
e. Distriction (ACCO) in the Control of the Control	<ul><li>Self adjuster ratchet noise.</li><li>Speed control interlock switch.</li></ul>	<ul> <li>Refer to Section 08-02 for diagnosis and service.</li> <li>Refer to Section 10-03.</li> </ul>
Vehicle Will Not Start With Clutch Pedal Fully Depressed	Improper adjustment of interlock switch, damaged switch or open or short-circuited wiring.	Refer to Section 10-03.     Refer to Section 08-02 for diagnosis and service.
ACTESM	r oggenera produkti * haufficient probad on revenue beering.	TC5441 sliebed nedwineupSito qued ेपूर्ण