DIAGNOSIS AND TESTING (Continued)

PINPOINT TEST J: EXCESSIVE BRAKE PEDAL EFFORT OR VACUUM LEAKS (Continued)

| TEST STEP | RESULT | Þ | ACTION TO TAKE |
|--|---|---|--|
| POWER SECTION TEST was control and evidence | | | in complete gale, find |
| Disconnect vacuum hose from booster vacuum check valve. Run engine at idle. Check vacuum supply with a vacuum gauge. | Above 40.5 kPa (12 in-Hg) and booster does not operate | | REPLACE booster. 18 REPEAT Step J1. |
| | Below 40.5 kPa (12 in-Hg) | | SERVICE or REPLACE vacuum hose and vacuur fittings. Also TUNE or |
| | | | SERVICE engine as required. REPEAT Step |
| | | | JI. |

TH7820A

PINPOINT TEST K: VACUUM BRAKE BOOSTER NOISE

| TEST STEP 199 ROLL PROVIDED TO STEP 199 ROLL PROVIDED TO STEP | | RESULT ▶ | ACTION TO TAKE | |
|---|--|--|--|--|
| K1 | VERIFY CONDITION | extrito (dodi-6 \ f.) mm0 | antività a towai paint | |
| Run engine at fast idle for 10 seconds or longer. Depress brake pedal and listen for noise. Compare results with known good system. Was a noise present? | | No ildinesse grint bris eco. Yes as alsed wrisen to thou | Vehicle OK. 3 2009 GO to K2. 3 2010 001 | |
| K2 | PUSH ROD ADJUSTMENT | episoed. If a seal is feaking, | BLEED brake system. REPLACE booster. REPEAT Step K1. | |
| | Check and adjust booster push rod. Is push rod adjustment OK? | Yes elace was bus belon. No was a electric beautoned and belong the second sec | | |

TH7814A

PINPOINT TEST L: SLOW OR INCOMPLETE BRAKE PEDAL RETURN

| ania e | # West to have best TEST STEP and a standard of the life | RESULT | | ACTION TO TAKE |
|--------|--|------------------------------------|---|--|
| L1 | VERIFY CONDITION OF CASSIC ALLEGE CONDITION | | | |
| | Run engine at fast idle while making several brake applications. Pull brake pedal rearward with approximately 44.5 N (10 lbs) force. Release the pedal and measure the distance to the toe board. Make a heavy brake application. Release the brake pedal and measure the pedal to toe board distance. The pedal should return to its original position. Did pedal return to original position? | Yes No Laste Foot tealingsite 1000 | | Vehicle OK. GO to L2. Se las Emporatorio de la constanta de l |
| L2 | BRAKE PEDAL BINDING | Yes No house mon years | | |
| | Check pedal to be sure it is operating freely. Is the pedal operating freely? | | Þ | REPLACE booster. CORRECT any sticking of binding. REPEAT L2. |

TH7811A

CLEANING AND INSPECTION

Service Precautions

 Grease or any other foreign material must be kept off lining surfaces and braking surfaces of rotor, and external surfaces of hub during service operation. In handling the rotor and caliper assemblies, avoid deformation of brake rotor and nicking or scratching of brake linings.

CAUTION: Do not pry on plastic piston with a screwdriver or other tools, as this will cause chipping.

- If a caliper piston is removed for any reason, piston seal must be replaced. Exercise care not to damage plastic piston by protecting it from contact with any metal or sharp objects.
- During removal and installation of a wheel assembly, exercise care not to interfere with and damage splash shield or bleeder screw fitting.
- Ensure vehicle is centered on the hoist before servicing any front end components to avoid bending or damaging splash shield on full right or left wheel turns.