DIAGNOSTIC TESTS (A-J) (Continued)

PINPOINT TEST C: ANTI-LOCK WARNING INDICATOR ON AFTER VEHICLE STARTS TO MOVE OR FALSE CYCLING OF ANTI-LOCK SYSTEM (Continued)

	GREET THE THE THE THE THE THE THE THE THE	RESULT ▶	ACTION TO TAKE
237	CHECK POWER TO RELAY COIL		A TIUORIO KORKO SE
3 04	Jumper Pins 34 and 60 at breakout box. Turn ignition to ON position. Measure voltage between Pin 86 and ground.	Over 10 volts length seems Less than 10 volts	GO to C38. SERVICE or REPLACE cable harness Circuit 532.
	- Obech organis or Laker breature box Prus Leek	218	
	539 PK/LB —— 85	ujiy between breakout box jili a 4	
	537 T/Y — 30 532 O/Y — 86	- Cinaze	a galanunas 21 - v
	462 P ——— S0	7011A FEBB 20	
	57 BK ————31		
	461 0 31		
		de and 60 at breakost box 1 W pasition.	
	7 PIN PUMP MOTOR RELAY CONNECTOR HARNESS SIDE H7781-B		* Does pump me
	111.01-0	OR OPERATION	
38	CHECK PUMP MOTOR RELAY COIL	protor relay from paint proton o	neg to encesse (
	Measure resistance between Pins 85 and 86 on	Yes .	GO to C39 .
	pump motor relay. Is resistance between 45 and 105 ohms?	No Saay ▶	REPLACE pump motor relay.
	MOTOR (-) 2 PUMP MOTOR RELAY H7780-B	MOTOR () 2 BY COLUMN CONNECTOR W7784 S	BEVERNOS A PERSONAL SE PROPERTO DE LA COMPANSIONA DEL COMPANSIONA DE LA COMPANSIONA DE LA COMPANSIONA DE LA COMPANSIONA DE LA COMPANSIONA DEL COMPANSIONA DE LA COMPANSIONA DE
39	CHECK CIRCUIT 539	- CONTRACTOR CONTRACTO	
	 Check for continuity between breakout box Pin 15 and Pin 85 on wire harness to pump motor relay connector. Is continuity present? 	Yes and entering most seems No should be no to seems to writing a great and a	GO to C40. SERVICE or REPLACE cable harness Circuit 539.
	539 PK/LB — 85 537 T/Y — 30		
	532 0/Y ———————————————————————————————————	The second contract of	
	462 P ——— S0		
	57 BK 31 - 31 - 31 - 31 - 31 - 31 - 31 - 31	en la reconserve de la filipia de la companione de la companione de la companione de la companione de la compa	
	461 O 31		
	7 PIN PUMP MOTOR RELAY CONNECTOR HARNESS SIDE H7781-B	STATE OF STA	