


DIAGNOSIS (Continued)

DIAGNOSIS (Continued)

Wiring Diagram

Except FF Vehicles



*PIN 19 ON 3.0L/3.2L SHO

A16105-A