

## J1930 Terminology List

New Term	New Acronyms/ Abbreviations	Old Acronyms/ Term
Shift Indicator Lamp	SIL	- SIL - Shift Indicator Lamp
Shift Solenoid	SS	- SS - Shift Solenoid
Signal Return	SIG RTN	- SIG RTN - Signal Return
Solid State Relay	SSR	- SSR - Solid State Relay
Spark Output	SPOUT	- SAW - Spark Angle Word
Speed Density	SD	- SD - Speed Density
Super High Output	SHO	- SHO - Super High Output
Supercharger/Supercharged	SC	- SC - Supercharger/Supercharged
Tachometer	TACH	- TACH - Tachometer
Three Way Catalytic Converter	TWC	- TWC - Three Way Catalytic Converter
Three Way + Oxidation Catalytic Converter	TWC+OC	- TWC & COC - Three Way Catalyst and Conventional Oxidation Catalyst
Throttle Body	TB	- TB - Throttle Body
Throttle Body Injection	TBI	- CFI - Central Fuel Injection
Throttle Position	TP	- TP - Throttle Position
Throttle Position Output	TPOUT	- TPOUT - Throttle Position Output
Torque Converter Clutch	TCC	- CCC - CCO - MCCC - Converter Clutch Control - Converter Clutch Override - Modulated Converter Clutch Control
Torque Converter Clutch solenoid	TCC solenoid	- LUS - MLUS - Lock Up Solenoid - Modulated Lock Up Solenoid
Transmission Control Module	TCM	- 4EAT Module
Transmission Control Switch	TCS	- TCS - Transmission Control Switch