
DIAGNOSIS (Continued)

item	Description	
1	Fuel Return	
2	Sender Ground	
3	Sender Positive	
4	Fuel Pump Positive	1 33,404(1)
5	Fuel Pump Negative	74,037 Open S Name (
6	Fuel Supply	

FF Vehicles



(bateritinoCi) alkillä Sibil		
1	Fuel Tank Drain	
2	Sender Ground Sender Positive	
3		
4	Fuel Pump Positive	
5	Fuel Pump Ground	
6	Fuel Return	
7	Fuel Supply	
	consumer D - 1974 By The My manager Consumer	