## **DIAGNOSIS AND TESTING (Continued)**

## **Remote Radio Control Functional Test**

Verify operation of remote radio control.

**Step 1.** Turn ignition to RUN or ACC. Turn radio on and verify radio operation.

Step 2. Test the following switch buttons:

MEMORY: Will advance to the previously stored stations in the preset buttons.

VOLUME: Volume will decrease when button is pressed on left (-) side and increase when pressed on right (+) side.

SEEK: Will advance the display forward only.

If any of these functions are inoperative but radio is otherwise functional, replace remote radio control switch.

## PINPOINT TEST A: ALL ELECTRONIC RADIO CONTROL FUNCTIONAL TEST

100	TEST STEP LANGE OF THE STEP	RE	SULT		ACTION TO TAKE
A1	VERIFY OPERATION OF RADIO				
X	Turn ignition to ON or ACC. Turn radio on.	Yes			GO to A3.
	Is radio display lit?    Is a select replaced a SSS   S	No		<b></b>	GO to A2.
A2	VERIFY SOUND FROM SPEAKERS		alaw.		- Argania se Maranga - 1938 - Argania se Maranga - Argania - 1938
	Is sound coming from speakers?	H <sub>Yes</sub>		<b></b>	GO to A17.
	Programme Programme Committee Commit	No			
	805 V383836 V000 Q08 B886	1.00			inoperative procedure
АЗ	AM INDICATOR TEST				Front (Ser Channel) Art
	Push the band or AM button. Is "AM" indicator lit?	Yes			
		No			REMOVE radio for
	Rear (PM Organis) - 14 Till Coman Grands	1 N 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			service.
A4	UP TEST TO THE PROPERTY OF THE				661753 606V 566963   773
	<ul><li>Depress "seek (&gt;)" or "scan" button and verify</li></ul>	Yes		<b>&gt;</b>	
	that number on display increases (if display reads 1610 AM or 107.9 FM display will not increase and	No		•	REMOVE radio for
	the "seek (>)" button should be depressed until	I v I and			service.
	display reads less than 1610 AM or 107.9 FM).				734 - Speaker Valde Cal
	Is "up" function OK?				
A5_	DOWN, TEST CONTRACT OF THE PROPERTY AND PROP				855   Space Valos Col 798
	<ul> <li>Depress "seek (&lt;)" button and verify that number on display decreases (if display reads 530 AM or 88.1 FM, display will not decrease and the "seek (&lt;)" button should be depressed until display reads</li> </ul>	Yes			GO to A6.
		No			REMOVE radio for
					service.
	greater than 530 AM or 88.1 FM).	II.X and			Para dangan angan para
A6	FAST UP TEST 0 88 950 168 168 168 168 168 168 168 168 168 168			************	
AO	Line in the Contract to the Co			31	
	<ul><li>Push AMS then SEEK (&gt;) button.</li><li>Is "fast up" function OK?</li></ul>	Yes			GO to A7.
	888 Fit From Ampleptus   Telephone September   Telephone September	No			REMOVE radio for service.
A7	FAST DOWN TEST			<u> </u>	OGIVICO.
	Push AMS then SEEK (<) button.	Yes		<b>&gt;</b>	GO to A8.
	Is "fast down" function OK?	Yes No		<b></b>	REMOVE radio for
		NO			HEMOVE radio for
A8	SCAN TEST ADDICTOR OF THE PROPERTY OF THE PROP				116 Accelled Switch Feed
ļ	Press SCAN button.	Yes		<b></b>	GO to A9.
	ls radio scanning to the next stations for five	No			REMOVE radio for
<u> </u>	second samplings?	X7 80084	A 10000 121		service.
	1 788 Un Utarres Serat Dat 15 (2), Gière Red Ch	X wide	yara (	8.1	noisega mora ku
	799 RM Chankel Signat Out 18 Change Black 1				
					. takken2 Inoff H3 G